

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Fairmont Elementary	Fountain	DF in classroom 6 near the door opposite the sink	10/22/2019	EPA-200.8	Lead	1.6		0.10	1.0
Fairmont Elementary	Fountain	DF opposite the door in classroom 7	10/22/2019	EPA-200.8	Lead	0.88	J	0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 5	10/22/2019	EPA-200.8	Lead	3.7		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 3	10/22/2019	EPA-200.8	Lead	2.5		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 4	10/22/2019	EPA-200.8	Lead	3.4		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 1	10/22/2019	EPA-200.8	Lead	3.2		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 2	10/22/2019	EPA-200.8	Lead	5.2		0.10	1.0

				EPA-200.8	Lead	3.1		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 9	10/22/2019	EPA-200.8	Lead	5.7		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 12	10/22/2019	EPA-200.8	Lead	2.2		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 11	10/22/2019	EPA-200.8	Lead	3.9		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 14	10/22/2019	EPA-200.8	Lead	19		0.10	1.0
Fairmont Elementary	Fountain	DF in classroom 13	10/22/2019	EPA-200.8	Lead	15		0.10	1.0

Fairmont Elementary	Tap	Tap in classroom 15	10/22/2019	EPA-200.8	Lead	20		0.10	1.0
---------------------	-----	---------------------	------------	-----------	------	-----------	--	------	-----

Fairmont